



Product Change Notification (PCN)

This document applies to all companies and branches of the Würth Elektronik eiSos Group.

- ☐ Major Change
☒ Minor Change

PCN Number: PCN_ConUMRF_20260918 Affected Series: WR-UMRF Affected Part Number: See table below PCN Date: 2026-06-18 (YYYY-MM-DD) Effective Date: 2026-09-18 (YYYY-MM-DD)	Change Category: ☐ Equipment/Location ☐ General Data ☐ Material ☐ Process ☐ Product Design ☒ Shipping/Packaging ☐ Supplier ☐ Software
Contact: Product Management Phone: +49 (0) 7942 - 945 5001 Fax: +49 (0) 7942 - 945 5179 E-Mail: pcn.eican@we-online.com	Datasheet Change: ☐ Yes ☒ No Attachment: ☐ Yes ☒ No

DESCRIPTION OF CHANGE:

Due to an improvement of the production capability, Würth Elektronik eiSos will remove the protective end caps from the product packaging.

The protective end caps were previously used as an additional packaging protection feature. Based on customer feedback and internal process optimization, they will be removed. Product protection during transportation remains ensured by bubble wrap before packing into the PE bag.


There will be no change in fit, form, function, quality or reliability of the product. The new revision of the affected part numbers will be sent out after the previous revision is out of stock (according to FIFO - first-in, first-out).

Affected part numbers:

636201040025	636201040030	636201040035	636201040040	636201040045	636201040050
636201040060	636201040065	636201040070	636201040075	636201040080	636201040083
636201040100	636201040110	636201040125	636201040140	636201040150	636201040200
636201040230	636201040250	636201040300	636201040350	636201040400	636201040450
636201040500	636201040650	636201041000	636201050025	636201050030	636201050035
636201050040	636201050045	636201050050	636201050060	636201050070	636201050075
636201050100	636201050110	636201050150	636201050200	636201050250	636201050300
636201050350	636201050400	636201050450	636201050500	636201050700	636201051000

DETAILS OF CHANGE:

Remove the protective tube on both ends of the UMRF plugs.



RELIABILITY / QUALIFICATION OF CHANGE:

There will be no change of the product, therefore no additional reliability or qualification testing was performed.
 The new packaging was checked according to internal quality standards.