


Product Name:	HPL - 677 DuraEV		
	DuraEV Socket Assembly		
Product Manager:	Tony Paul P		
Subject:	Notification of Change with Immediate Effectivity		
Distribution:	Affected Customers		
Type of Change:	Design Change		
Change Description:	Introduction of metal latch and twine lanyard 		
Reason for Change:	To reduce the damage on the connector due to abuse, plastic latch and flat TPU lanyard is replaced with metal latch and a twine lanyard. The old version of Dura EV can be supported till October 31st based on customer request. Afterwhich only new version of Dura EV product with metal latch and twine lanyard shall be available.		
Affected Parts:	See Affected Parts.xls file		
Effective Date of Change:	November,01 2026		
Last Time Buy Date:			
Earliest Disty Return Date:			
Last Time Shipment Date			
Datasheet Attached?	NA		
Qual/Test Data Attached?	NA		
Samples Availability Date:	15 August ,2026		
Available Alternatives?			
Questions?	Contact your local ACS Representative, or Product Manager		
	Tony Paul P / Product Manager		
	Tony.Paul@amphenol-fci.com		

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .