

Product Name:	HPL – 676	
	Flexlock RA header Part nbr series 10158557	
Product Manager:	Jennifer Zhang	
Subject:	Notification of Planned Change	
Distribution:	Affected customers	
Type of Change:	Process Change	
Change Description:	Develop new 4 cavity mold for Flexlock RA Header 12pin & 30pin housing, and this mold can be reserved to change over 10-40p if having new demand increasing in the future	
Reason for Change:	To expand Flexlock RA Header housing capacity and reduce supply delivery shortage risk.	
Affected Parts:	See Affected Parts.xls file	
Effective Date of Change:	September, 14 2026	
Last Time Buy Date:	NA	
Earliest Disty Return Date:	NA	
Last Time Shipment Date	NA	
Datasheet Attached?	Yes	
Qual/Test Data Attached?	Yes	
Samples Availability Date:	07 September ,2026	
Available Alternatives?		
Questions?	Contact your local ACS Representative, or Product Manager	
	Jennifer Zhang / Product Manager	
	Jennifer.Zhang@amphenol-fci.com	

Note:

Customers should contact Product Line Manager (or their local Amphenol Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .