



PRODUCT CHANGE NOTIFICATION

INDUCTORS



Bourns® SRR1210 and SRR1210A Series Shielded Power Inductors

Change in RI Core Design

Riverside, California – August 19, 2026 – As part of our continuous improvement efforts, effective June 1, 2027, Bourns will change the RI Core design for the SRR1210 and SRR1210A Series Shielded Power Inductors. A positioning structure will be added to the RI core to enhance structural robustness. A list of affected part numbers is included below.

Affected Part Numbers

SRR1210A-1R0Y	SRR1210A-330M	SRR1210A-471M	SRR1210-120M	SRR1210-181M
SRR1210A-1R8Y	SRR1210A-390M	SRR1210A-561M	SRR1210-150M	SRR1210-221M
SRR1210A-2R2Y	SRR1210A-470M	SRR1210A-681M	SRR1210-180M	SRR1210-271M
SRR1210A-3R3Y	SRR1210A-560M	SRR1210A-821M	SRR1210-220M	SRR1210-331M
SRR1210A-4R7Y	SRR1210A-680M	SRR1210A-102M	SRR1210-270M	SRR1210-391M
SRR1210A-5R6Y	SRR1210A-820M	SRR1210-1R0Y	SRR1210-330M	SRR1210-471M
SRR1210A-6R8Y	SRR1210A-101M	SRR1210-1R8Y	SRR1210-390M	SRR1210-561M
SRR1210A-8R2Y	SRR1210A-121M	SRR1210-2R2Y	SRR1210-470M	SRR1210-681M
SRR1210A-100M	SRR1210A-151M	SRR1210-3R3Y	SRR1210-560M	SRR1210-821M
SRR1210A-120M	SRR1210A-181M	SRR1210-4R7Y	SRR1210-680M	SRR1210-102M
SRR1210A-150M	SRR1210A-221M	SRR1210-5R6Y	SRR1210-820M	SRR1210-102M2
SRR1210A-180M	SRR1210A-271M	SRR1210-6R8Y	SRR1210-101M	
SRR1210A-220M	SRR1210A-331M	SRR1210-8R2Y	SRR1210-121M	
SRR1210A-270M	SRR1210A-391M	SRR1210-100M	SRR1210-151M	

The form, fit, and function of the finished products will remain the same. The quality and reliability of the inductors should be improved. Traceability will be maintained through lot code and date code.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications for verification of satisfactory performance.

Implementation dates are as follows:

Date that products manufactured with the current RI core will cease: **2027-05-31**

Date that deliveries of products manufactured with the new RI core angle will begin: **2027-06-01**

First date code using the above changes **2722**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC26140



If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).